# LINE UP

Step1 CLEAN ALL SURFACES
-clean the shelf and LINE-UP rail by using cloth.
-remove all (if any) impurity.

Step2 PLACEMENT OF ADHESIVE POINTS
-place adhesive points in intervals of 175mm (in positions of spectacle holders) to achieve optimal spacing.
-additionally place one adhesive point on every edge of the LINE-UP profile (apx 5mm from the edge) aswell.



Step3 INSER SPECTACLE HOLDERS
-use this direction as shown




www.framedisplays.com
22821 Silverbrook Center Drive, Suite 140
Sterling, VA. 20166, USA

Phone
U.S. 1-877-274-9300

Other international+1 703.435.7770
Fax 416-981-7112 / 703-435-3180 (USA)
info@framedisplays.com